



**CTO Direction**

**Equivalent measures for consignments non-compliant with VEHICLE-ALL**

**CTO direction code for recording in Quantum: CTO Plants: 2017 0005**

Pursuant to section 27(1)(d)(iii) of the Biosecurity Act 1993 I, give the following directions for measures, different from those required by section 4.3 in the Import Health Standard (IHS): *Vehicles, Machinery and Tyres* – VEHICLE-ALL, that may be applied to consignments of vehicles and machinery for the management of the risk of the Brown Marmorated Stink Bug.

Treatment with:

Sulfuryl fluoride at 16g/m<sup>3</sup> for 12 hours with a minimum dose reading of 8 g/m<sup>3</sup> at a temperature of 10°C or greater to achieve a CT of 144 g.h/m<sup>3</sup>.

All other relevant sections of the IHS: VEHICLE-ALL for vehicles and machinery must be complied with.

This direction takes effect from the 8 February 2017, and may apply to multiple consignments of vehicles and machinery which are not compliant with the measures required by section 4.3 in the IHS: VEHICLE-ALL. This CTO direction is valid for 2 years from the date of signing unless earlier amended or revoked.

**Chief Technical Officer**

Date: 20/2/17